

SLQ Wiki Fabrication Lab 2024/10/04 11:21

When you are cutting your job

- Are you and (everybody in the room) wearing your PPE?
- Are you and (everybody in the room) standing behind the yellow safety line?
- Are you alert and ready to hit the emergency stop if required?
- Are you ready to hit the pause button to clear debris?

DO NOT GO NEAR THE SPINDLE UNTIL YOU CAN CONFIRM IT HAS STOPPED SPINNING

LINKS

CNC Router Operations

Other Operations - Staff Only

Multicam CNC Induction