



# Level 2 and 3 Inductions

SLQ Wiki Fabrication Lab 2024/11/11 19:59

# Level 2 and 3 Inductions

## Level 2 Independent Machinist Level 3 Supervisor/ Facilitator Induction

Individuals seeking to complete this level of induction need to demonstrate an advanced understanding of the tool/ plant. The Edge uses an Recognition of Prior Learning (RPL) style process demonstrate competency.

### Key Criteria

Individuals must demonstrate competency in

Training participants in the safe and correct use of the Tool/ Plant. identify and preempt unsafe, improper or inefficient use of the tool /plant by participants. training and supporting participants' application of workflow up to and around the tool/ plant training participants basic maintenance and care a working knowledge and be able to support participant application of stock control and administrative procedures connected to the use the tool basic troubleshooting on the tool/ plant delivering competency based assessment and possess a capacity/ experience to support participants with a range of backgrounds and learning styles to demonstrate competency.

### Evidence of Competency

**Three forms of evidence of competency are required for each criteria. In this case the three forms of evidence will be**

1. Assessor Observation Report during training simulation
2. Candidate written response to Safe Work Instructions and Induction Materials
3. Candidate notes on Level 1 Induction Paperwork and FLS Procedures.

as well as any other evidence candidates wish to present ( CV examples of work etc)

Observations can be recorded on the below word doc.

I2\_3assessorobs.docx

Subsequent to the Assessor finding candidate competent, their details are recorded on O:drive