



PETG - Do one piece then wait 5 minutes.
Seperate pieces when lasering
and watchout for buckling of material